



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	Filled in by Pl	20
	ember 22, 2022 Date received	
House No/ . Advance	ed Research and vation Center Received by	Name & Signature
Location : Visayas	S State University Designation/ Position	:
Nar Designation/	Theresa P. Loreto ne & Signature rector, ARIC	: er
Please check and specify the nature of work requested		
 □ Vehicle Repair □ Welding Works □ Machining works (lathe, shaper, drill press, etc.) 	☐ Carpentry & Furniture Works☐ Plumbing Works☐ Instrumentation equipment & Laboratory instrument	☐ Electrical Works☑ Heating, Ventilating, Air conditioning & Refrigeration☐ Others (specify):
Materials/Supplies/Parts: Available Not Available		
Brief Description of Repair and Maintenance		
Air conditioning unit check and repair - AC is not blowing cold air		
Filled in by PPO personnel		
Part/Supplies/Materials Required	Manpower Requirement	Estimated hours/days to finished
	Filled in by the requesting party at	ter the conduct of repair and maintenance
	Service Satisfaction	OVER-ALL RATING
	☐ 1. Not Satisfied	☐ 1 Poor ☐ 2 Fair
	2. Slightly Satisfied	☐ 3 Good ☐ 4 Very Good
	3. Moderately Satisfied	☐ 5 Excellent
	4. Very Satisfied5. ExtremelySatisfied	Comments & Suggestion

Vision:

A globally competitive university for science, technology, and environmental

onservation.

Mission:

Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 2 FM-PPO-09 v0 02-28-2022