



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting party	Filled in by PPO
Date filed 4 VAW. 2022	Date received :
Building/Facility/ House No/ Apartment No./ Department APT 72	Received by Name & Signature
Location 1916 owne Oring	Designation/ Position Maintenance
Requesting party NANCY VOUNTS	111111111111111111111111111111111111111
Designation/ Head, OlfA Position Arror, Pry. V	
To be accomplished in three (3) copies	
Please check and specify the nature of service req	uest
Audio System (amplifier, speakers and microphones)	Tent installation/s
With Lights? Yes No	Setup Location:
Setup Location: Date & Time Needed:	No. of tent:
	Fabrication/s (new cabinets, furniture, metal works
Estimated Duration (hrs):	and other fabrications not considered as repair and
Land preparation, plowing & harrowing	maintenance) Installation/s (tarpaulin, signage, new lock & knobs &
Location/Area covered: other installation not considered as repair and	
Estimated passing trip.	maintenance)
Site development, levelling, scrapping & backfilling	Machining works (lathe, shaper, drill press & etc.)
Location:	
Hauling (Construction materials, office equipment & etc.)	
From: To:	
Brief Description of Service Request	
T've the ich: Prink Drain and DxWtem	
Landry Ordinage voyetens (ingr. Votenzona's toilet drainage system (1e aking)	
Engr. Votenzona's	tojet drainage vxvtem (120/909)
Trilet Tonk Pla	~VL
, 0,1, 7	
Service Conducted by Name & Signature	To be filled by the requesting party after
PPO Unit :	Service request conducted Overall Service Satisfaction
	Not Satisfied
Conformed by (Requesting Party) :	and the second s
Name & Signatu	2. Slightly Satisfied
	3. Moderately Satisfied
Checked by (PPO Unit Head)	4. Very Satisfied
Name & Signatu	re
	5. Extremely Satisfied