



PHYSICAL PLANT OFFICE

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

REQUEST INFORMATION	
Filled in by requesting party	Filled in by PPO
Date filed : 9/17/2024	Date received :
Building/Department : DEPARTMENT OF AGRANDIN	Received by Name & Signature
Location : UPPER CAMPUS	Designation/Position :
Requesting party : <u>LU2 </u>	Request Reference : Number
Designation/Position : DA, Head	
Contact no./Email :	
Please check and specify the nature of work requested:	
☐ Vehicle Repair ☐ Carpentry & Fu	rniture Works Electrical Works
☐ Welding Works ☐ Plumbing Work	□ 111' 1/-1' A:-
☐ Machining works (Lathe, shaper, drill press, etc.) ☐ Instrumentation equipment & Laboratory instrument ☐ Others (specify in the brief description below)	
Brief Description of the Nature of Work Requested	
Leaking pipes at DA Room 201	
INSPECTION (Filled in by PPO Personnel)	
Date of Inspection: Time started:	[AM] [PM] Time ended: [AM] [PM]
	For Outsourcing Repair and Maintenance
Materials/Parts Manpower Required:	Catimated haves (days)
☐ Available ☐ Available	Schedule of repair:
□ Not Available □ Not Available	
Conducted: PPO Maintenance Personnel/Name & Sign	Confirmed: Name and Signature
Designation/Position	Designation/Position
ACCOMPLISHMENT	
Filled in by PPO Personnel	Filled in by Requesting Party
Conducted by PPO Maintenance Personnel	Service Satisfaction OVER ALL RATING
Date & Time Started	□ 1. Not Satisfied □ 2. Slightly Satisfied □ 3. Good □ 2. Fair □ 4. Very Good
	□ 4. Very Satisfied □ 5. Extremely Satisfied □ 5. Excellent
	Comments & Suggestion
Checked : PPO Head/Director (Name and Signature)	Name &Signature
Notes:	Designation/Position