

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting party:	Filled in by PPO
Date filed : December 10, 2021	Date received :
Building/Facility/ House No/ Apartment No./ Department ADE Building	Received by Name & Signature
Location : DBM	Designation/ . Position
Requesting party : ANGELITA L PARADERO	Maintenance : control number
Designation/ : Head, DBM	
To be accomplished in three (3) copies	
Please check and specify the nature of service re	quest
Audio System (amplifier, speakers and microphones)	Tent installation/s
With Lights? Yes No	Setup Location:
Setup Location: Date & Time Needed:	No. of tent:
Estimated Duration (hrs):	Fabrication/s (new cabinets, furniture, metal works
Land preparation, plowing & harrowing	and other fabrications not considered as repair and maintenance)
Location/Area covered:	Installation/s (tarpaulin, signage, new lock & knobs &
Estimated passing trip:	other installation not considered as repair and
Site development, levelling, scrapping &	maintenance)
backfilling	Machining works (lathe, shaper, drill press & etc.) Others
Location:	(specify):
Hauling (Construction materials, office equipment & etc.)	
From: To:	•
Brief Description of Service Request	
Installation of Plastic Barriers of two classrooms. (ADE 215 & 216)	
(In Preparation for the limited force to-face classes)	
Service Conducted by	
Name & Signat	ure To be filled by the requesting party after service request conducted
PPO Unit :	Overall Service Satisfaction
Conformed by (Requesting Party) :	1. Not Satisfied
Name & Signat	ure 2. Slightly Satisfied
Checked by (PPO Unit Head) : Name & Signature	3. Moderately Satisfied
	5. Extremely Satisfied