



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting party			Filled in by PPC	)		
Date filed	: September 19,	2022	Date received	:		
Building/Facility/	<u>-</u>					
House No/	:		Received by			
Apartment No./ Department				Nam	e & Signature	
· ·	-		Designation/		o a o.g. a.a.	
Location	·		Position	:		
			Document	:		
Requesting party	:	UD AN	control number			
Designation/	CHARLIE S. AI	NDAN				
Designation/ Position	: Head, DM	et				
Please check and specify the	e nature of service req	uest				
Audio System (amplif	ier, speakers and	П Т4	ent installation/s			
☐ microphones)	N.					
With Lights? Yes Setup Location:	With Lights? Yes No         Setup Location:           Setup Location:         No. of tent:					
Date & Time Needed: Tent size:						
	(hrs):				metal works and other	
				cabinets, rumiture, sidered as repair ai		
Land preparation, plo		74	,	ar a span ar		
Location/Area covered: Installation/s (tarpaulin, signage, new lock & knobs &						
Estimated passing trip: installation not considered as repair and maintenance)						
Site development, levelling, scrapping & Machining works (lathe, shaper, drill p					ess & etc.)	
Location:	Location: Landscaping (Design and Installation)					
Hauling (Construction materials, office equipment & etc.)			Location/Area covered:			
From: To:			Other/s (Specify): wiring of the 2 air conditioner units at the computer room of the Department of Meteorology			
	stimates ( <i>Drafting, floo</i> st estimate, site inspect	r				
and the likes)						
	Brief De	scription of	Service Request			
There are 2 units of aircon a				d, thus tis request.		
				, , , , , , , , , , , , , , , , , , , ,		
		Filled in by the requesting party after the conduct of service request				
Conducted		Service S	Satisfaction	OVER-ALL RATING		
<sub>hv</sub> . PPO F	Personnel	1. Not \$	Satisfied	☐ 1 Poor	☐ 2 Fair	
PPO Unit		_ 2. Sligh	tly Satisfied	☐ 3 Good	☐ 4 Very Good	
	<sub>[</sub>	☐ 3. Mode	erately Satisfied	☐ 5 Excellent	•	
05110		☐ 4. Verv	Satisfied	Comments & Suggestion		
Checked & Engr. MARIO Verified by: VALENZONA	LILIO P.	_ `	emely Satisfied	30		
	ead/Director	_ J. LAUC	ory Janonea			
	& Signature)					
		Name ar	nd Signature			
			-			
	L					