

Republic of the Philippines  
**VISAYAS STATE UNIVERSITY**  
Visca, Baybay City, Leyte  
**SUPPLY & PROPERTY MANAGEMENT**

## INSPECTION & ACCEPTANCE REPORT

Supplier: **GRIMIT LABORATORY FURNITURES & EQUIPMENT CORP.**

IAR No: 25-07-0921

P.O No.: **VSU-GOODS-24-64-006 (TF)**

Date: 2025-07-02

Office/Dept: **NARC**

**486,000.00**

TF-2024-07-01415

No.	UNIT	DESCRIPTION	Quantity		Date Received	Balance	Remarks
			Per P.O	Actual			
1	unit	Laboratory tables with sink	2	2	2025-07-01 #: DR-1182/SI-01311	0	Completed

**Specification:**

Speci?cation:

Dimensions: approx. 124 cm x 70 cm x 90 cm

Frame: Steel structure

Cabinet Material: High-quality galvanized steel sheet

Surface Coating: Epoxy powder

Table Top:

Material: at least 16 mm thick corrosion-resistant black phenolic resin board

Edge Sealing: 25.4 mm thickness

Slideway: Three-section slide rail, no noise

Hinges: Open type high-quality, self-closing

Handle: Aluminum (assumed as handle type not speci?ed)

Sink Dimensions: 55 cm x 45 cm

2	unit	Laboratory working tables with reagent rack	2	2	2025-07-01 #: DR-1182/SI-01311	0	Completed
---	------	---	---	---	-----------------------------------	---	-----------

**Specification:**

Speci?cation:

Dimensions: Approx. 200 cm x 124 cm x 90 cm

Frame: Steel structure

Cabinet Material: High-quality galvanized steel sheet

Surface Coating: Epoxy powder

Tabletop:

Material: At least 16 mm thick corrosion-resistant black phenolic resin board

Edge Sealing: 25.4 mm thickness

Hardware & Components:

Slideway: Three-section slide rail, no noise

Hinges: Open-type, high-quality, self-closing

Handle: Aluminum, dark type

Additional Features:

Reagent rack shelf

Top cupboards

INSPECTION

ACCEPTANCE

Date Inspected: 7/1/15

Date Received: 7/1/15


☐ Inspected, verified and found in order  
as to quantity and specifications

☒ Complete

☐ Others: \_\_\_\_\_

☐ Partial

  
**CLINT C. SARVIDA**  
Inspector

  
**VIVIAN V. BALBARINO**  
Head, Supply & Property Management