



VISAYAS
STATE UNIVERSITY

**OFFICE OF THE
PRESIDENT**



Management
System
ISO 9001:2015
www.tuv.com
ID: 3108898745

14 August 2023

MEMORANDUM NO. 814
Series of 2023

T O: Engr. Mario Lilio P. Valenzona
Director, General Services Division

Attn: Engr. Marlon G. Burlas

R E: Checking of Circuit Breakers/Electrical Wirings and other Related Electrical Connections of all VSU Buildings

The recent incident of the Department of Biological Sciences (DBS) that happened just today is very alarming. The building almost caught fire as the circuit breaker exploded twice then emitted smoke and fire. Fortunately, the utility worker was fast enough to put up the fire.

With this, you are hereby directed to check all the circuit breakers and the electrical wiring of all the buildings in VSU. After the inspection, you are also directed to furnish this office with your report together with your recommendation, categorized upon the most urgent and corresponding budgetary requirements. Kindly submit your report on September 1, 2023.

Please do this immediately.


EDGARDO E. TULIN
President

OFFICE OF THE PRESIDENT

2/F Administration Building, Visayas State University
PQWW+RJM, Baybay City, Leyte, Philippines 6521
Email: op@vsu.edu.ph | Website: www.vsu.edu.ph
Phone: +63 53 565 0600 Local 1000



Page 1 of 1
FM-OOP-01
V4 05-09-2023
No. 23-814