## OFFICE PERFORMANCE COMMITMENT & REVIEW FORM (OPCR)

I, MARLON G. BULAS Head of the WATER AND SEWERAGE SYSTEM MAINTENANCE UNIT commits to deliver and agree to be rated on the attainment of the following targets in accordance with the indicated measures for the period: July - December 2018

MARLONG. BURLA

Ratee

Noted:

MARIO LILIO VALENZONA
Director, GSO

Personnel Composition	Position Title/Designation	Number	
Head	Unit Head	1	
Regular staff	Adm. Aide V	1	
Casual Staff	Foreman	1	
	Sub-TOTAL Sub-TOTAL	3	
Job lorder	Plumber	9	Rating Equivalents:
			5 - Outstanding
			4 - Very Satisfactory
			3 - Satisfactory
	Sub Total	9	2 - Fair
	TOTAL	12	1 - Poor

UMFO6- General Administration Support Services OVPAF-MFO4, Physical Facilities Development and Maintenance GSD, MFO4, Water and Sewerage Maintenance

MFOs/PAPS	Success Indicators	Persons Reponsible	Target	Actual Accomplishme nt	% as of Dec. 31	Rating				
						Q¹	E <sup>2</sup>	T <sup>3</sup>	A <sup>4</sup>	Remarks
WSSMU-MFO1- Water Distribution System for new and major repairs/ renovations	No. of Water distribution system in new and renovated/implemented Academic and Research Buildings	M.G. BURLAS, G. ARPOCEPLE, A.	3	5	166.67%	5	5	4	4.667	
	The state of the s		1	1	100.00%	5	5	4	4.667	
	ivo. of water distribution system in new		1	2	200.00%	5	5	4	4.667	

	No. of Water distribution system in new and renovated/implemented Student/ staff housing units		1	2	200.00%	5	5	4	4.667	
WSSMU-MFO2- Plumbing System improvement and maintenance inside Buildings	No. of plumbing systems improvements/repairs inside Academic and research buildings	M.G. BURLAS, G. ARPOCEPLE, A. SINGSON and 9 Job Orders	85	92	108.24%	5	5	4	4.667	as per job request
	No. of Plumbing system improvements/repairs inside Administrative Buildings		78	80	102.56%	5	5	4	4.667	as per job request
	No. of Plumbing system improvements/repairs inside IGP Buildings and structures		46	50	108.70%	5	5	4	4.667	
	No. of Plumbing system improvements/repairs inside Student/Staff Housing units		50	65	130.00%	5	5	4	4.667	as per job rerquest
WSSMU,MFO3- Water Distribution System repair and maintenance outside Buildings	No. of Water Distribution Lines repaired/maintained	M.G. BURLAS, G. ARPOCEPLE, A. SINGSON and 9 Job Orders	15	30	200.00%	5	5	4	4.667	
					TOTAL				42	
				Avarage Rating				4.667		
					Ajectival Rating				VS	

	REMBERTO A. PATINDOL	MARIO LILIO VALENZONA	EDGARDO E. TULIN
Planning Office	PMT	Director, GSD	President
Date:	_ Date:	Date	Date

1 - Quality

2- Efficiency

3 - Timeliness

4 - Average