OH 3013

Visayas State University

HEAVY EQUIPMENT & LIGHT VEHICLE MAINTENANCE UNIT

Visca, Baybay City, Leyte

OFFICE PERFORMANCE COMMITMENT & REVIEW (OPCR)

I, Marlon G. Burlas, Head, HELVMU, commits to deliver and agree to be rated on the attainment of the following targets in accordance with the indicated measures for the period <u>January to June</u>, 2018.

MARLON G. BURLAS Head, HELVMU

Dáte: _____

MARIO LILIO P. VALENZONA

Date: ____

					4				
MFO	Success/Performance Indicator (PI)	Units/Persons Responsible	Target	Actual Accomplishment		F	Rating		Remark
Descrip- tion					Quality	Efficiency	Timeliness	Average	
UMFO 6: Ge	neral Administration and Support S	Services							
HELVMU MF	O 1. Administrative and Facilitative	Services							
Pl 1: Numbe forms prepara	r of letter and standard government	R. M. Sanico, E. Dargantes	1,870	1,900	5	5	5	5.00	HELVMU Office
	documents and job requests receive, recorded	E. Dargantes	400	410	5	4	3	4.00	HELVMU Office
PI 3: No. of s stock cards	pare parts & lubricants record on	E. Dargantes	330	338	5	4	3	4.00	HELVMU Office
PI 4: Docum	ents Filing	E. Dargantes	200	210	4	4	3	3.67	HELVMU Office
No. of rooms	loors and windows opened cleaned and maintained g/surroundings cleaned & maintained	R. M. Sanico & 3 JO	40	50	5	4	3	4.00	HELVMU Office & Motorpool bldg.

HELVMU MFO 2. Ground Improvement (New Construction, etc.)

P2 1: No. of grounds (sites) filled-up, scraped, cleared and improved	. B. Castanas . J. Caballero . 3 JO's	8	8	5	5	5	5.00	. Garbage area; Agronomy; VSU Gym area; New Library; Garden show area; Supply & Gasoline Station area; ATI; PCC area
P2 2: No. of areas maintained	. B. Castans; 4 JO's	5	6	5	5	4	4.67	Oval (Upper & Lower); F & G show area; Highway P. Fence & Borders; GSD surroundings; & Beach area
HELVMU MFO 3. Ground Maintenance								
P3 1: No. of irrigation and drainage canals maintained	B. Castanas; 2JO's	5	6	5	5	4	4.67	Nangka & Mabolo Drive; Calbiga-a & Pangasugan; Exptl. Area; Beach & Highway area
P3 2: NO. of perimeter fence/gates fabricated & maintained	N. Manla; 3 JO's	6	6	5	4	3	4.00	GSD; Highway P. Fence; F & G show area; VSU Garden Resort; Guard Post 1 & 2; Nangka & Mabolo Drive
P3 3: No. of irrigation & drainage canals maintained	3 JO's	6	6	5	4	4	4.33	. Nangka & Mabolo Drive; Calbiga-a & Pangasugan; experimental areas; Beach & Highway area
HELVMU MFO 4. Land Preparation (Research	Related)							
P4 1: No. of land areas prepared based on Job Request	. B. Castanas . J. Caballero . 2 JO's	9	10	5	4	4	4.33	Philrootcrops; NCRC-V; DPBG; DASS; Eco-Farmi; DAS; DOH; Lab.High Sch.; PCC; NARC
P4 2: No. of hauling/trips based on job request	B. Castanas; . J. Caballero . 3 JO's	160	200	5	5	4	4.67	Research Center; Diff. departments/Offices

HERVMU	MFO 5.	Repair of	Heavy	& Light	Vehicles

P5 1: No. of body repair & fabrication (Metal & Steel Work)s	R. M. Sanico; N. Manla; E. Orendain; 2 JO's	3	3	5	4	4	4.33	. Isuzu Elf 350; Rosa Bus 02; Toyota Land Cruiser (Blue)
P5 2: No. of under chassis repair, welding & servicing	A. Armada; R. Muana; C. Albiso; E. Orendain; 2 JO's	36	36	5	5	4	4.67	. Light Vehicles (13 units); Trucks & Buses (10units); Heavy and Farm Equipment (13 units)
P5 3: No. of engine tune up & servicing	R. Muana; C. Albiso; R. Oracion; A. Armada; 1JO	8	13	5	5	4	4.67	. These include other departments vehicles/equipment repaired & serviced by HELVMU
P5 4: No. Transmission/Differential repair	A. Armada; R. Muana; B. Castanas; C. Albiso; 2JO's	4	5	5	5	5	5.00	. Hi-Ace (Tolosa); Land Cruiser (White); Ford Tractor; PESMU; WSSMU Jeep
P5 5. No. of engine overhauling/changing	A. Armada; R. Muana; E. Orendain; 1 JO	4%	4	5	4	4	4.33	. T-Land Cruiser; Hi-Ace; PESMU; WSSMU Jeep
P5 6: No. of motor rewinding & electrical repair	R. Oracion	130	135	5	4	4	4.33	. Heavy & Light Vehicles repaired and maintained; include other departments
P5 7: No. of spare parts machining & fabrication	V. Meliton	9	10	5	4	4	4.33	. These include other departments vehicles/equipment repaired & serviced by HELVMU
P5 8: No. of repainting of vehicles & equipment	3 JO's	2	3	5	4	4	4.33	. Rosa Bus 02; T-Land Cruiser(Blue); Isuzu Elf 250
P5 9: No. of tire change & vulcanize	1JO	90	95	5	4	4	4.33	Bicycle; Motorcycle; HELVMU & department vehicles

			· · · · · · · · · · · · · · · · · · ·					
P5 10: No. of steering (Power/Manual) & hydraulic pump repair	A. Armada; R. Muana; 1JO	2	3	5	4	3	4.00	. Backhoe; Payloader; Tractor
P5 11: No. of shop services based on job				1	<u> </u>	<u> </u>		Based on Job Request
requests		50	70	4	4	3	3.67	
HELVMU MFO 6. Operation and maintenance of	fvehicle		-					•
P6 1: No. of trips served	Marlon G. Burlas; I. Laplana; N. Rabanos; C. Cutamora; A. Borneo; C. Rabanos A. Banayag; N. Quimco	1230	1238	5	3	3	3.67	VSU Vehicles
P6 2: No. of vehicles & farm equipment maintained	A. Armada; R. Muana; C. Albiso; N. Manla; E. Orendain; 3 JO's	30	36	3	2	2	2.33	Light Vehicles (13 units); Trucks & Buses (10 units); Heavy & Farm Equipments (13 units)
HELVMU MFO 7. Frontline Services					1	1 1		1
PI 1. Efficient and customer-frienly frontline service	Zero percent complaint from clients served	90%	100%	5	5	4	4.67	
Best practices/new initiatives								
Total Over-all Rating							111.00	
Average Rating				0.00	0.00	0.00	4.44	
Adjectival Rating		***************************************			Very	Satisfact	ory	
Received by:	Received by: Calibrated			Recommending Approval:				Approved: EDGARDO E. TULIN Provident
Planning Office							President	

Date:

Date:

Date: _

Date: