OFFICE PERFORMANCE COMMITMENT & REVIEW FORM (OPCR)

I, MARLON G. BURLAS Head of the WATER AND SEWERAGE SYSTEM MAINTENANCE UNIT commits to deliver and agree to be rated on the attainment of the following targets in accordance with the indicated measures for the period: July to December 2017

Noted:

Approved:

MARLON G BURLAS Ratee MARIO LILIO VALENZONA

Director, GSD

G**A**RDO E. TULIN

President

Personnel Composition	Position Title/Designation	Number	
Head	Unit Head	1	1
Regular staff	Adm. Aide V	1	
Casual Staff	Plumber Foreman	1	
	Sub-TOTAL		
Job Order	Plumber Welder	1	Rating Equivalents:
	Pump Operator	2	5 - Outstanding
	Plumber	2	4 - Very Satisfactory
	Laborers	4	3 - Satisfactory
	Sub Total	9	2 - Fair
	TOTAL	12	1 - Poor

UMFO6- General Administration Support Services

OVPAF-MFO4, Physical Facilities Development and Maintenance

GSD, MFO4, Water and Sewerage Maintenance

MFOs/PAPS	Success Indicators	Persons Reponsible	Actual Target Accomplis	Actual Accomplishm	% as of Dec.	. Rating				Remarks
WSSMU-MFO1- Water Distribution System for new and major repairs/ renovations	PI 1.1: No. of Water distribution system in new and	M. BURLAS, G. ARPOCEPLE and A. Singson 9 Job Orders	4	ent 6	100.00%	Q ¹	E ²	T ³	A ⁴ 4.66667	
	renovated/implemented Academic and Research Buildings PI 1.2: No. of of Water distribution system in new and renovated/implemented Administrative Buildings		1	2	100.00%	5	5	4	4.66667	
	PI 1.3: No. of Water distribution system in new and renovated/implemented IGP Building and structures		1	2	100.00%	5	5	4	4.66667	
	PI 1.4: No. of Water distribution system in new and renovated/implemented Student/ staff housing units		1	3	100.00%	5	5	4	4.66667	
	PI 2. 1: No. of plumbing systems improvements/repairs inside Academic and research buildings		50	90	100.00%	5	5	4	4.66667	

WSSMU-MFO2- Plumbing System	PI-2.2: No. of Plumbing system improvements/repairs inside Administrative Buildings		10	85	100.00%	5	5	4	4.66667		
improvement and maintenance inside Buildings	PI-2.3: No. of Plumbing system improvements/repairs inside IGP Buildings and structures		10	55	100.00%	5	5	4	4.66667		
a.	PI-2.4: No. of Plumbing system improvements/repairs inside Student/Staff Housing units		40	55	100.00%	5	5	4	4.66667		
WSSMU,MFO3- Water Distribution System repair and maintenance outside	PI-3.1: No. of Water Distribution Lines repaired/maintained		15	25	100.00%	5	5	4	4.66667		
Total Over all Rating									42		
Average Rating									4.66667		
by:	Calibrated by: REMBERTO A. PATINDOL	Recommending Ap		PO A PATIN		Appro		الما	RDO E. TU	JLIN	
Planning Office	PMT		Vice President				– Fresident				
Date:	Date:										
			Date					Date			

3 - Timeliness

4 - Average

2- Efficiency

1 - Quality